



























































Some reliability design consequences

- Used industrial parts spec'd to -40°C
- Tin-lead solder used wherever possible
- Electrolytic caps replaced with higher reliability plastic caps
- High stability crystal oscillator (~\$7 Toyocom replaced by ~\$70 Corning)
- Found and replaced component types that did not operate properly at low temperature.

























OUTLOOK		
• 2005-06	up to 10 str	ings >amanda)
• 2006-07	14-16	
• 2007-08	16-18	
• 2008-09	16-18	
• 2009-10	<u>14-18</u> 71-79 str	ings













